


Project Name		Project No.	Co-ords: E - N	Hole Type Rotary
Location:			Level: 19.10 m AOD	Scale 1:50
Client:			Dates:	Logged By

Well	Water Strikes	Rotary Coring				Depth (m)	Level (m AOD)	Legend	Stratum Description
		Depth (m)	TCR	SCR	RQD				
		9.10-11.60 9.10-11.60	40	25	30	9 NI 160 320			Remaining Detail : 9.46m - 9.66m : fracturing. Detail 9.73m - 9.73m : 9.73m : Fracture: 315 36 NW Detail 9.84m - 9.84m : 9.84m : Fracture: 318 36 NW Detail 9.94m - 9.94m : 9.94m : Fracture: 196 41 S
		11.60-12.10					11.60	7.50	11.20m - 11.38m : Weathered; discolouration, weakening and fracturing. 11.40m - 11.60m : Fracture: 180 51 S. Quartz veining.
		11.60-13.00 12.10-13.00	99	41	42	NI NI 55 110			11.60m - 13.00m : Moderately weak, grey, medium-grained SANDSTONE with quartz veining. Partially weathered, pitting and discolouration of core, clay smearing on fracture surfaces. Fractures are dipping between 36 degrees and 61 degrees, orientated northwest - southeast. 11.67m : Fracture: 165 36 SE 11.70m : Fracture: 160 70 SE 11.79m : Quartz veining. 11.83m : Fracture: 310 36 NW 11.95m : Fracture: 196 21 SW 11.99m : Fracture: 320 41 NW 12.02m : Fracture: 316 46 NW 12.43m - 13.58m : Quartz veining. 12.74m - 13.00m : Weathered; discolouration, weakening and fracturing. Non-intact.
		13.00-14.50 13.00-14.50	100	7	17	NI NI 85 190			13.00m - 18.05m : Moderately weak, purple, fine-grained SANDSTONE. Partially weathered, pitting and discolouration of core, clay smearing on fracture surfaces. Fractures are dipping between 26 degrees and 81 degrees, orientated northwest - southeast. 13.10m - 13.50m : Fracture: 355 85 N 13.63m - 13.87m : Weathered; pitting, weakening and discolouration. 13.70m : Fracture: 349 46 N 13.90m - 14.39m : Fracture: 183 85 S 14.12m - 12.26m : Highly fractured, non-intact. 14.59m : Fracture: 341 41 NE 14.77m - 14.88m : Highly fractured, non-intact. 14.97m : Fracture: 320 36 NW 15.50m : Fracture: 317 36 NW 15.50m - 15.90m : Highly fractured, non-intact. 15.60m - 16.00m : Fracture: 321 41 NW 16.57m - 16.87m : Highly fractured, non-intact.
		14.50-15.50 14.50-15.50	84	10	30	6 NI 155 310			17.00m : Fracture: 349 70 N 17.34m : Fracture: 325 70 NW 17.38m - 17.45m : Weathered; weakening and clay infilling. 17.41m - 17.57m : Fracture: 331 36 NW 17.45m : Highly fractured, non-intact. 17.59m : Fracture: 095 35 E 17.63 : Quartz veining 17.80m : Quartz veining 17.82m : Fracture: 336 45 NE
		15.50-17.00 15.50-17.00	73	2	0	NI NI 57 115			18.05m - 19.80m : Moderately weak, purple, thinly laminated, fine-grained SANDSTONE, with quartz veining. Partially weathered, pitting and discolouration of core, clay smearing on fracture surfaces. Fractures are dipping between 36 degrees and 51 degrees, orientated northwest - southeast. 18.05m : Fracture: 305 36 NW 18.09m : Fracture: 335 36 NW 18.33m : Fracture: 330 50 NW 18.40m : Fracture: 331 50 NW
		17.00-18.05 17.00-18.05	97	32	22	7 NI 175 350	18.05	1.05	
		18.05-19.35 18.05-19.50	95	34	47	10 NI 120 240			
		19.35-20.20 19.50-20.20	100	40	54	NI NI FI	19.80	-0.70	
				TCR	SCR	RQD			

Remarks: Standpipe installed.

Continued next sheet